


Swing Clamps with Sturdy Swing Mechanism Top flange type, with optional position monitoring, double acting, max. operating pressure 350 bar



Advantages


- 5 sizes available
- Compact design partially recessible
- High clamping force at low pressures
- Sturdy swing mechanism
- Insensitive against high flow rates
- Indexing of the clamping arm in a specified position is possible
- Special swing angle easily realizable
- Standard FKM wiper
- Metallic wiper optional
- Screw counterbores coverable
- Position monitoring available in six variants
- Hydraulic and pneumatic ports integrated in the flange
 - the flange
- Mounting position: any

Installation and connecting possibilities Pipe thread



Pneumatic position monitoring integrated


Monitoring of the clamping arm in clamping position (adjustable)




Monitoring of the piston in unclamping position




Both controls combined






3 1.85

Issue 4-13 E




Position monitoring as accessories Switch rod for external sensors



Pneumatic position monitoring in clamping and unclamping position

184XB



Electrical position monitoring in clamping and unclamping position



Application

Hydraulic swing clamps are used for clamping of workpieces, when it is essential to keep the clamping area free of straps and clamping components for unrestricted workpiece loading and unloading.

Due to the sturdy swing mechanism and the manifold possibilities of position monitoring these swing clamps are particularly suited for

- Automatic manufacturing systems
- Clamping fixtures with workpiece loading via handling systems
- Transfer lines
- Test systems for motors, gears and axes
- Assembly lines
- Special machine tools

Description

The hydraulic swing clamp is a pull-type cylinder where a part of the total stroke is used to swing the piston.


The favourable area ratio (piston/piston rod) allows high clamping forces already at relatively low oil pressures.

Due to the sturdy swing mechanism the angle position of the clamping arm remains the same after a slight collision with the workpiece during loading or unloading. Also a collision during the clamping process is not critical. When using high flow rates the swing speed is

limited by installed throttle points. The FKM wiper at the piston rod can be protected against coarse and hot swarf by an optionally available metallic wiper (see page 6). The different possibilities of the position monitoring are presented at the side.

Important notes see page 6.

Versions: Code letters A, B, C, D, H, P, Q Dimensions • Swing angles



Actual issue see www.roemheld.com

Subject to change without prior notice

B 1.853 / 4-13 E

2

Technical characteristics

	0 degree		1843-X000-023M	1844-X000-024M	1845-X000-030M	1846-X000-036M	1847-X000-039M
	Swing direction 90° ccv		1843-X090-L23M	1844- <mark>X</mark> 090-L24M	1845-X090-L30M	1846-X090-L36M	1847- <mark>X</mark> 090-L39M
Part-no.	Swing direction 90° cw		1843-X090-R23M	2.3 1844-X090-R24M	1845-X090-R30M	1846-X090-R36M	1847-X090-R39M
z Weight, approx.		[mm] [kg]	11 1.7	11.5 2.3	12 3.9	6	15 8.9
x +0.3/-0.2 / x max. ¹⁾		[mm]		90 / 91.7	106 / 107.7	118.5 / 118.8 12	128 / 129.6
w2		[mm]	84 / 85.2	21	24.5		128 / 120 6
w1		[mm]	22.5 22	24.5	28	32 25	35
W		[mm]	12	13	17	20	20.5
v2		[mm]	36	36	40	41	41
v1		[mm]	31	31	35	36	36
V		[mm]	26.4	26.4	30.4	30.4	30.4
u2		[mm]	27	33.5	41.5	44.5	53.5
u1		[mm]	18.5	24.5	28	32	35
u		[mm]	36.5	42	50	53	62
t		[mm]	7.5	9	10	10	11
Øs		[mm]	30	30	33	33	33
Ør		[mm]	45	52	60	76	90
p3		[mm]	18.4	15.4	17.4	15.4	17.4
Ø p2 H13		[mm]	11	15	18	20	20
Øp1		[mm]	6.6	9	11	13	13
р		[mm]	M6	M8	M10	M12	M12
0		[mm]	98	105	118	136	146
n		[mm]	26.5	31	37	44	50
m1		[mm]	52	52	56	56	56
m +0.4/-0.7 ²⁾		[mm]	62.4	63.9	74.9	80.3	84.8
L1		[mm]	70	81	95	105	120
L		[mm]	50	62	75	88	100
k		[mm/°]	0.091	0.093	0.12	0.152	0.183
h1 +0.4/-0.3 / h1max.1)		[mm]	165 / 166.3	178 / 179.8	207 / 208.8	237.5 / 237.9	257 / 258.7
h +0.4/-0.3 / h max.1)		[mm]	161 / 162.3	174 / 175.8	203 / 204.8	233.5 / 233.9	254 / 255.7
G			G 1/8	G 1/8	G 1/4	G 1/4	G 1/4
g		[mm]	M14x1.5	M18x1.5	M20x1.5	M28x1.5	M35x1.5
Øf		[mm]	27	30	36	40	55
Ø d3		[mm]	10	10	12	12	12
Ø d2		[mm]	33	42	54	54.5	75
Ø d1		[mm]	28	38	45	48	60
Ød		[mm]	16	20	25	32	40
c1		[mm]	12	14	14	18	20.5
С		[mm]	28.5	31.5	35	43	56
b		[mm]	40	45	54	66	76
а		[mm]	37	45	54	66	76
Piston Ø		[mm]	23	28	36	45	55
Oil to return		[cm ³]	9.6	14.8	30.5	57.2	92.7
Oil volume / stroke		[cm ³]	4.9	7.2	15.8	28.3	43.7
piston area	Unclamping	[cm ²]	4.15	6.15	10.17	15.9	23.75
Effective	Clamping	[cm ²]	2.14	3.01	5.27	7.86	11.19
(see page 4)	Unclamping	[cm ³ /s]	20	28	60	110	185
Max. flow rate	Clamping	[cm ³ /s]	10	14	32	57	87
Min. operating pressure	9	[bar]	30	30	30	30	30
Total stroke ±0.2		[mm]	23	24	30	36	39
Swing stroke		[mm]	11	12	15	21	24
Clamping stroke		[mm]	12	12	15	15	15
Effective clamping force	9	[kN] [kN]	S	ee diagram page 3 or	r calculation of the cla	mping force on page	
Max. pulling force (350			7.5	10.5	18.4	27.5	39.1


Code letter X see page 2. ¹ h / h1 / x = upper edge piston

h max. / h1 max. / x max. = upper edge nut

M = Option metallic wiper (see also page 6)

²⁾ m = lower edge clamping arm

Effective clamping force with accessory clamping arm as a function of the oil pressure




* Clamping force for other lengths see page 4.




B 1.853 / 4-13 E


Accessories - Clamping arms • Plastic covers • Metallic wipers Calculation of the flow rate • Calculation of the clamping force




Clamping arm complete with angle



Special clamping arm 1. Connecting dimensions



2. Admissible flow rate Q*



In the chart on page 3, the admissible flow rates for clamping and unclamping with the clamping arms (accessories) are specified. Longer special clamping arms have a higher torque of inertia. To avoid an overload of the swing mechanism, the flow rate has to be reduced:

2.1 Moments of inertia are known


$$Q_{L} = Q_{e} \star \sqrt{\frac{J_{e}}{J_{L}}} cm^{3}/s$$

- $Q_1 =$ Flow rate with special clamping arm
- Q_{e}^{-} = Flow rate as per chart (page 3)
- J_e = Moment of inertia of the clamping arm (accessory) with contact bolt (chart)
- J₁ = Moment of inertia special clamping arm

* Only for vertical mounting position!

a b	[mm] [mm]	58	75	93	100	15.1
	[mm]				120	154
	[· · · · · · ·]	17	22	26	32	38
С	[mm]	28	36	45	60	72
c1	[mm]	14	20	23	28	36
Ød f7	ĺmmĺ	16	20	25	32	40
Ød1 +0.1/+0.05	[mm]	15.8	19.8	24.8	31.8	39.8
е	ĺmmĺ	35	50	60	80	100
f	[mm]	16	16	22	26	34
g	ĺmmĺ	M14x1.5	M18x1.5	M20x1.5	M28x1.5	M35x1.5
g1	ĺmmĺ	M8	M10	M12	M16	M20
h min/max	ĺmmĺ	5/45	6/64	7/70	9/85	12/100
Ø k +0.1	ĺmmĺ	3	3	3	3	3
1+0.5	ĺmmĺ	9	10	10	10.5	11
m ±0.05	ĺmmĺ	7.8	9.8	12	15	19
n	[mm]	11	17	20	20	20
0	[mm]	6	10	12	20	20
p	[mm]	22.5	27	32	39	44
q	[mm]	9	10	11	12.7	12.7
Ør	[mm]	20	24.5	31	34.5	46
S	[mm]	2.5	4	4	4.5	5
t	[mm]	11	17.5	19	19	19
ŭ	[mm]	17	18	21	19	25
v1	[mm]	6	7	8	6	12
v2	[mm]	4	4	5	5	5
w1	[mm]	18	24	26	26	26
w2	[mm]	21	27	30	30	30
Part-no. Clamping arm	[rinii]	<u> </u>	21	00	00	00
- with contact bolt		0354-152	0354-153	0354-154	0354-155	0354-259
Weight, approx.	[kg]	0.19	0.39	0.69	1.43	2.64
Moment of inertia of J e	[kgm ²]	0.00011	0.00046	0.0011	0.00398	0.01198
- without thread g1	[(9))]	3548-660	3548-661	3548-803	3548-804	3548-919
Weight, approx.	[kg]	0.16	0.34	0.62	1.28	2.34
Moment of inertia of J e	[kgm ²]	0.00007	0.00033	0.00084	0.00298	0.00896
- complete with angle	[rgiii]	0354-156	0354-157	0354-158	0354-159	0354-175
Angle bracket complete		0184-003	0184-004	0184-005	0184-005	0184-005
Plastic cover**		3300-685	3300-684	3300-683	3300-682	3300-682
Metallic wiper		0341-104	0341-107	0341-105	0341-100	0341-101
Spare nut		3527-092	3527-014	3527-099	3527-015	3527-048
Tightening torgue	[Nm]	3527-092 16	3527-014 30	3527-099 42	3527-015 90	3527-046 160
ngmening lorque	נואוו]	10	30	42	90	100

Special clamping arm



= 2

** Order 4 off swing clamps

2.2 Moments of inertia not known

This simplified calculation is only applicable for clamping arms of the above shape.

Example: Swing clamps 1843

L = 70 mm

e = 35 mm as per above chart

ᠿ

length


 $Q_a = 10 \text{ cm}^3/\text{s}$ (as per chart page 3) $\frac{x}{e} \frac{L}{e} = \frac{70 \text{ mm}}{35 \text{ mm}}$

 \rightarrow y = 0.35

- Flow rate factor as per diagram
- 3. Max. flow rate

$$Q_{L} = y * Q_{e} = 0.35 * 10 \text{ cm}^{3}/\text{s} = 3.5 \text{ cm}^{3}/\text{s}$$

4. Min. clamping time
as per diagram
$$\rightarrow$$
 approx. 1.4 s



Adm. flow rate and clamping time as a function of the clamping arm extension

Clamping force and admissible operating pressure

Effective clamping force (general)

$$F_{sp} = \frac{p}{A + (B * L)} \le F_{adm.}$$
 [kN]

[kN]

Admissible clamping force

$$F_{adm} = \frac{C}{L}$$

Admissible operating pressure
$$p_{adm} = \frac{D}{L} + E \le 350$$
 [bar]

A, B, C, D, E = constants as per chart

Constant

	1843	1844	1845	1846	1847
А	46.64	33.15	18.98	12.72	8.93
В	0.335	0.17	0.073	0.04	0.027
С	210	420	900	1760	3000
D	9795	13926	17078	22386	26805
E	70.26	71.33	65.44	70.36	81.78

F_{adm} =
$$\frac{C}{L}$$
 = $\frac{210}{70}$ = 3 kN

2. Admissible operating pressure

$$p_{adm} = \frac{D}{L} + E = \frac{9795}{70} + 70.26 = 210 \text{ bar}$$

Römheld GmbH

B 1.853 / 4-13 E

Accessory for 184XB0XX • Pneumatic position monitoring (not adjustable) Pneumatic valve

Application

A prerequisite for automated processes of workpiece clamping are hydraulic clamping elements whose position can be monitored at anv time.

The pneumatic position monitorings signal the following conditions by closing two bore holes:

- 1. Piston extended, clamping arm in offposition.
- 2. Piston in clamping area, clamping arm in clamping position.

By the pressure increase in the pneumatic line an electro-pneumatic pressure switch or a differential pressure switch can be actuated.

The electrical switching devices are integrated in the electric control so that on the clamping fixture no electricity is required.

Description

The pneumatic position monitoring consists of the stainless control housing with fit signal sleeve, to be connected to the switch rod of the swing clamp by means of the delivered screw. Four fixing screws are included in our delivery.

Pneumatic port


Drilled channels

The swing clamp with the mounted position monitoring is inserted into the location hole and is immediately ready for use with the mounted O-rings.


Hose connection

Remove the plugs M5 and screw-in connecting nipple M5 (accessory) Sealing to the flange area is made by the two O-rings.

Monitoring by pneumatic pressure switch Part-no.



For the evaluation of the pneumatic pressure built-up standard pneumatic pressure switches can be used. It is possible to monitor with one pressure switch up to 8 position monitorings connected in series (see circuit diagram). It has to be considered that process-safe functioning of pneumatic position monitorings is only guaranteed with throttled air and system pressure. The nominal values are indicated below technical characteristics.




Technical characteristics

Connection		O-ring or thread M5
Nominal diameter	[mm]	2
Max. air pressure	[bar]	10
Range of operating	[bar]	35
pressure Differential pressure*) a	at	
3 bar system pressure	[bar]	min. 1.5
5 bar system pressure	[bar]	min. 3.5
Air flow rate **)	[l/min]	1020
	- 1	

- *) Required pressure drop if one or several position monitorings are not operated.
- **) For measuring the air flow rate appropriate devices are available. Please contact us.

Function chart



0 = Passage 1 = Closed


Swing clamps		1843B0XX	1844B0XX	1845B0XX	1846B0XX	1847B0XX	
L	[mm]	129	136	172	190	200	
L1	[mm]	50	50	73	73	73	
Swing angle (see page 2)							
0 or 90°		0353-913	0353-913	0353-914	0353-916	0353-956	
15 to $75^\circ = 2$ (graduation of		3-913-0 <mark>XX</mark>	0353-913-0 <mark>XX</mark>	0353-914-0 <mark>XX</mark>	0353-916-0 <mark>XX</mark>	0353-956-0 <mark>XX</mark>	


Pneumatic valve

Spare part for versions C, H, P and Q

Switching range 2 - 9 mm Switching range 2 - 10 mm Max. operating pressure Max. tightening torque Function charts see page 2.







Römheld GmbH

Application

Electrical position monitorings signal the following conditions due to damping of two inductive proximity switches:

- 1. Piston extended, clamping arm in offposition.
- 2. Piston in clamping area, clamping arm in clamping position.
- З. Piston in final position, no workpiece inserted. *)
- *) If this function is not desired, e.g. in setting mode, the proximity switch can be adjusted so that the switch is still damped at the stroke end (see function chart).

Description


The electrical position monitoring consists of the housing with two adjustable inductive proximity switches and one switching cam fixed at the switch rod of the swing clamp.

The fixing screws are included in our delivery. The housing can also be mounted turned by 180°. The radial distance of the proximity switches to the switching cam should be 0.5 mm. It is secured by means of a set screw M4. After untightening of the locking screw M4 the proximity switches can be axially displaced.

Please note:

Careful design is required. According to the corresponding application conditions, safety measures have to be planned and checked later on.

Inductive position monitorings are not suitable for the use in coolant and swarf areas.



Technical characteristics

Operating voltage	1030 V DC
Max. residual ripple	15 %
Max. constant current	200 mA
Switching function	interlock
Output	PNP
Body material	stainless steel
Thread	M 8 x 1
Code class	IP 67
Environmental temperature	-25+70 °C
LED Function display	yes
Protected against short circuits	yes
Connection type	Right angle plug
Length of cable	5 m

Part-no).					
Swing c	lamps	1843B0XX	1844B0XX	1845B0XX	1846B0XX	1847B0XX
L	[mm]	131	138	172	190	200
L1	[mm]	52	52	73	73	73
With swi plug	itch and plug	0353-905	0353-905	0353-915	0353-915	0353-915
Without plug	switch and	0353-906	0353-906	0353-917	0353-917	0353-917

.

Important notes

Swing clamps must only be used for clamping of workpieces in industrial applications and may only be operated with hydraulic oil. They can generate very high forces. The workpiece, the fixture or the machine must be in the position to compensate these forces.

In the effective area of piston rod and clamping arm there is the danger of crushing. The manufacturer of the fixture or the machine is obliged to provide effective protection devices.

The swing clamp has no overload protection device. When mounting the clamping arm, the clamping arm or the hexagon socket in the piston have to be backed up for tightening and untightening the fixing nut. During loading and unloading of the fixture and during clamping a collision with the clamping arm has to be avoided.

Remedy: Mount position adaptor.

Operating conditions, tolerances and other data see data sheet A 0.100.

Wiper system

The standard FKM wiper has a high chemical resistance against most cooling and cutting fluids.

The optional metallic wiper protects the FKM wiper against mechanical damage due to big or hot swarf.

It consists of a radially floating wiping disk and a retaining disk.

The metallic wiper can be delivered already mounted ("M") or as an accessory for retrofitting (see page 4).


Attention!


The metallic wiper is not suitable for dry machining or minimum quantity lubrication. Also in applications with very little grinding swarf, the standard FKM wiper has a better protection effect.

If there is any danger that small particles stick to the piston rod, the metallic wiper disk can also be replaced by a hard plastic disk.

Throttling of the flow rate

A flow rate throttling always has to be effected in the supply line to the swing clamp. This avoids a pressure intensification and thereby pressures exceeding 350 bar.







0

0

Unclamped

Clamped 1

adiustable

·10°

0 = On

Swing

angle

1 = Off

0

adjustable

<u>1mm 1mm</u>

Clamping

stroke

6