Electronic differential pressure gauge with display

Datasheet

Subject to technical alteration Issue date: 14.08.2020 • A110





» APPLICATION

Electronic alternative to conventional pressure gauges: reliable monitoring and display of air pressure in ventilation and air conditioning.

» SECURITY ADVICE – CAUTION



The installation and assembly of electrical equipment should only be performed by authorized personnel.

The product should only be used for the intended application. Unauthorised modifications are prohibited! The product must not be used in relation with any equipment that in case of a failure may threaten, directly or indirectly, human health or life or result in danger to human beings, animals or assets. Ensure all power is disconnected before installing. Do not connect to live/operating equipment.

Please comply with

- Local laws, health & safety regulations, technical standards and regulations
- Condition of the device at the time of installation, to ensure safe installation
- This data sheet and installation manual

Before mounting, commissioning and operation, make sure that the right pressure gauge has been selected in terms of measuring range, design and, due to the specific measuring conditions, the suitable wetted medium. Only install and maintain pressure gauges by qualified personnel authorized by the plant operator. Failure to comply with applicable regulations may result in serious personal injury and / or property damage.

» NOTES ON DISPOSAL



As a component of a large-scale fixed installation, Thermokon products are intended to be used permanently as part of a building or a structure at a pre-defined and dedicated location, hence the Waste Electrical and Electronic Act (WEEE) is not applicable. However, most of the products may contain valuable materials that should be recycled and not disposed of as domestic waste. Please note the relevant regulations for local disposal.

(F

» PRODUCT TESTING AND CERTIFICATION

Declaration of conformity

The declaration of conformity of the products can be found on our website https://www.thermokon.de/.

» USE ENCLOSURE WITH UV AND WEATHER RESISTANCE


After some time, outdoor mounted plastics can lose their color and quality. Therefore, all USE housings are made of special white polycarbonate (PC). The light-stable colorants and additives are used to achieve optimum protection of the polymer while maintaining color stability. The titanium dioxide used is specially developed for polycarbonate and offers excellent UV protection through the reflection of the entire light spectrum including the UV component by 340 nm. This effectively counteracts the otherwise occurring photochemical polymer degradation. The colors stay full for a long time without fading. The material is also resistant to cold and frost.

» TECHNICAL DATA

Measuring values	differential pressure
Medium	air, non-aggressive gases, non-flammable gases
Power supply	Battery 1,5 V (Type AAA), included in delivery
Power consumption	max. 60 mW (in operation) max. 1 mW (standby)
Operating temp range	-10+50 °C
Measuring range	02500 Pa
Accuracy pressure	±1,5 % of measuring range
Max. working overpressure	34 kPa
Display	LCD 29x35 mm with RGB backlight
Enclosure	enclosure USE-M, PC, pure white, cover PC, transparent, UV resistant
Protection	IP65 according to EN 60529
Connection mechanical	connection tube: PVC, soft
Ambient condition	max. 85% rH short term condensation
Delivery content	incl. battery (type AAA), 2 plastic duct flanges, 2 m PVC connection tube, incl. mounting base enclosure USE-M pure white, incl. universal mounting set (cover screw, self-drilling screws, dowels, spax screws and screw cover)

» FUNCTION

When inserting the battery, observe the polarity according to the printing in the device.



» COMMISSIONING

Select	battery
-> LRO3	(Alkaline)
FR03	(Lithium)

Zero-point correction!		
Pressure		
Pa	Z	
0	0	
Interval	Threshold	
Min	Pa	
1	500	

Main menu
Zero-point correction
->Threshold
Interval
Cancel

Main menu
Zero-point correction
Threshold
Interval
->Cancel

Select battery

To provide an approximate battery status message when the battery is about to go out, it is recommended to specify the type of battery. Standard delivery Alkaline.

Battery status

With a remaining capacity of <10%, the message "Battery status <10%" appears in the status line when the display is activated and the RGB backlight lights up yellow as long as the display is active. A battery change should be made as soon as possible.

Zero-point correction!

After the first commissioning or a battery change, a first zero correction is necessary. When the display is activated, the "Zero Correct!" Message appears in the status line, and the RGB backlight turns amber while the display is active

Main menu | Zero-point correction

With this selection, a zero point correction is executed directly. It is recommended to do the correction every 12 months. Before the zero point correction, both hoses must be disconnected from the pressure connections + and -. Otherwise the zero point correction will be executed incorrectly.

Main menu | Threshold

If the entered value is exceeded, the display flashes cyclically red. When the display is activated, "Limit Error" appears in the status bar. The error display remains until the pressure falls below the entered limit again. The limit value is adjustable in the range 0.. + 2500 Pa.

Main menu | Interval

The device measures the pressure cyclically according to the entered interval. When reading by activating the display by pressing a button, a new measurement is performed immediately. Interval adjustable $1 \mid 2 \mid 5 \mid 10 \mid 15$ minutes.

Main menu | Cancel

measuring interval and limit value.

Exits the configuration menu and returns to the main screen. The menu will also exit automatically if no key is pressed for 10 seconds

The main screen displays the measured value, proportion

of the measured value in relation to the entered limit value,

Main screen

Device status ok Pressure Pa 0 0 Interval Min Pa 1 500

Battery status < 10%				
Pressure				
	Рa	Z		
	0	0		
Interval		Threshold		
	Min	Pa		
	1	500		


Main menu
->Zero-point correction
Threshold
Interval
Cancel

Main menu		
Zero-point correction		
Threshold		
->Interval		
Cancel		

» MOUNTING ADVICES


- A prerequisite for the operation is a proper installation of the battery as well as the pressurized connection line
- In order to connect the device, the process lines must be unpressurized
- Consider the suitability of the device for the medium to be measured
- Consider maximum pressures

» **OPERATION**



There is a capacitive button under the cover (see picture). With an immediate touch on the cover the display can be turned on without the cover must be opened. The display remains on for 10 seconds (not adjustable).

» DIMENSIONS (MM)



»ACCESSORIES (INCLUDED IN DELIVERY)

Battery 1,5V AAA (Micro) Mounting base enclosure USE-M 2 m PVC connection tube KKS40 kit · 2 plastic duct flanges · 4 mounting screws 4x20	Item No. 739351 Item No. 631228 Item No. 484268 Item No. 430135
Mounting kit universal • Cover screw + screw cover• 2 Rawlplugs • 2 Screws (countersunk head) • 2 Screws (rounded head)	Item No. 698511

»ACCESSORIES (OPTIONAL)

T-hose connector for pressure hoses Ø=4 mm (10 pcs) Adapter 90° angle for pressure hoses Ø=4 mm Metal duct connector MKS40 Metal duct connector MKS100 Item No. 668323 Item No. 668330 Item No. 265138 Item No. 302531